

NAVAIR RESCUE REPORT

*An Update for Navy Aircraft Firefighters
and Aircraft Handlers*



Inside this edition:

- [Protective Clothing Board](#)
- [ABMA Agenda Item Update](#)
- [NATOPS Manuals Update](#)
- [Questions from the Fleet](#)
- [Webbing Sling Update](#)

Volume No: 02

Issue No: 1

Mar 2002

PMA-251-F3/5



NAVAIR RESCUE REPORT



An Update for Navy Aircraft Firefighters and Aircraft Handlers

The Shipboard Protective Clothing Board (SPCB) is working towards improving flight/hangar deck and flight line protective clothing. Current initiatives are improved and fire retardant (FR) trousers, jerseys and foul weather coats. Other improved items already available in the stock system now are

1. Improved flight deck boot Price \$70.45 pr

3 N	8430-01-464-5345	6.5 W	8430-01-464-5940	10.5 N	8430-01-464-6998
3 R	8430-01-464-5389	6.5 XW	8430-01-464-5942	10.5 R	8430-01-464-7613
3 W	8430-01-464-5394	7 N	8430-01-464-5943	10.5 W	8430-01-464-7616
3 XW	8430-01-464-5401	7 R	8430-01-464-5944	10.5 XW	8430-01-464-7619
3.5 N	8430-01-464-5419	7 W	8430-01-464-5945	11 N	8430-01-464-7648
3.5 R	8430-01-464-5421	7 XW	8430-01-464-5946	11 R	8430-01-464-7626
3.5 W	8430-01-464-5422	7.5 N	8430-01-464-5947	11 W	8430-01-464-7638
3.5 XW	8430-01-464-5423	7.5 R	8430-01-464-5948	11 XW	8430-01-464-7655
4 N	8430-01-464-5431	7.5 W	8430-01-464-5950	11.5 N	8430-01-464-7656
4 R	8430-01-464-5433	7.5 XW	8430-01-464-5952	11.5 R	8430-01-464-7664
4 W	8430-01-464-5434	8 N	8430-01-464-6023	11.5 W	8430-01-464-7659
4 XW	8430-01-464-5435	8 R	8430-01-464-6024	11.5 XW	8430-01-464-7669
4.5 N	8430-01-464-5436	8 W	8430-01-464-6025	12 N	8430-01-464-7863
4.5 R	8430-01-464-5437	8 XW	8430-01-464-6027	12 R	8430-01-464-7625
4.5 W	8430-01-464-5438	8.5 N	8430-01-464-6030	12 W	8430-01-464-7652
4.5 XW	8430-01-464-5440	8.5 R	8430-01-464-6032	12 XW	8430-01-464-8037
5 N	8430-01-464-5908	8.5 W	8430-01-464-6033	12.5 N	8430-01-464-8040
5 R	8430-01-464-5909	8.5 XW	8430-01-464-6034	12.5 R	8430-01-464-7693
5 W	8430-01-464-5910	9 N	8430-01-464-6866	12.5 W	8430-01-464-7707
5 XW	8430-01-464-5911	9 R	8430-01-464-6889	12.5 XW	8430-01-464-7725
5.5 N	8430-01-464-5912	9 W	8430-01-464-6893	13 N	8430-01-464-7757
5.5 R	8430-01-464-5913	9 XW	8430-01-464-6907	13 R	8430-01-464-7835
5.5 W	8430-01-464-5914	9.5 N	8430-01-464-6928	13 W	8430-01-464-8012
5.5 XW	8430-01-464-5915	9.5 R	8430-01-464-6941	13 XW	8430-01-464-8050
6 N	8430-01-464-5917	9.5 W	8430-01-464-6947	13.5 N	8430-01-464-8059
6 R	8430-01-464-5918	9.5 XW	8430-01-464-6984	13.5 R	8430-01-464-8064
6 W	8430-01-464-5919	10 N	8430-01-464-6954	13.5 W	8430-01-464-8091
6 XW	8430-01-464-5920	10 R	8430-01-464-6966	13.5 XW	8430-01-464-8108
6.5 N	8430-01-464-5921	10 W	8430-01-464-6972	14 N	8430-01-464-8120
6.5 R	8430-01-464-5922	10 XW	8430-01-464-6993	14 R	8430-01-464-8140

NAVAIR RESCUE REPORT



An Update for Navy Aircraft Firefighters and Aircraft Handlers

2. MK1 float coat/bladder assembly (Fully assembled when purchased). Price per unit approx. \$180.00.

SMALL, WHITE -	NSN 4220-01-487-2940	LARGE, WHITE -	NSN 4220-01-487-3300
SMALL, RED -	NSN 4220-01-487-2950	LARGE, RED -	NSN 4220-01-487-3619
SMALL, GREEN -	NSN 4220-01-487-2963	LARGE, GREEN -	NSN 4220-01-487-3625
SMALL, BLUE -	NSN 4220-01-487-2972	LARGE, BLUE -	NSN 4220-01-487-3647
SMALL, BROWN -	NSN 4220-01-487-2978	LARGE, BROWN -	NSN 4220-01-487-3650
SMALL, YELLOW -	NSN 4220-01-487-2980	LARGE, YELLOW -	NSN 4220-01-487-3652
SMALL, PURPLE -	NSN 4220-01-487-3190	LARGE, PURPLE -	NSN 4220-01-487-3655
MEDIUM, WHITE -	NSN 4220-01-487-3192	X-LARGE, WHITE -	NSN 4220-01-487-3657
MEDIUM, RED -	NSN 4220-01-487-3201	X-LARGE, RED -	NSN 4220-01-487-3659
MEDIUM, GREEN -	NSN 4220-01-487-3206	X-LARGE, GREEN -	NSN 4220-01-487-3661
MEDIUM, BLUE -	NSN 4220-01-487-3210	X-LARGE, BLUE -	NSN 4220-01-487-3663
MEDIUM, BROWN -	NSN 4220-01-487-3239	X-LARGE, BROWN -	NSN 4220-01-487-3666
MEDIUM, YELLOW -	NSN 4220-01-487-3294	X-LARGE, YELLOW -	NSN 4220-01-487-3667
MEDIUM, PURPLE -	NSN 4220-01-487-3297	X-LARGE, PURPLE -	NSN 4220-01-487-3669

MK1 cover only. Price per unit approx. \$80.00 each

SMALL, WHITE -	NSN 4220-01-487-2937	MEDIUM, PURPLE -	NSN 4220-01-487-3296
SMALL, RED -	NSN 4220-01-487-2946	LARGE, WHITE -	NSN 4220-01-487-3299
SMALL, GREEN -	NSN 4220-01-487-2961	LARGE, RED -	NSN 4220-01-487-3618
SMALL, BLUE -	NSN 4220-01-487-2968	LARGE, GREEN -	NSN 4220-01-487-3624
SMALL, BROWN -	NSN 4220-01-487-2977	LARGE, BLUE -	NSN 4220-01-487-3645
SMALL, YELLOW -	NSN 4220-01-487-2979	LARGE, BROWN -	NSN 4220-01-487-3649
SMALL, PURPLE -	NSN 4220-01-487-3189	LARGE, YELLOW -	NSN 4220-01-487-3651
MEDIUM, WHITE -	NSN 4220-01-487-3191	LARGE, PURPLE -	NSN 4220-01-487-3654
MEDIUM, RED -	NSN 4220-01-487-3198	X-LARGE, WHITE -	NSN 4220-01-487-3656
MEDIUM, GREEN -	NSN 4220-01-487-3204	X-LARGE, RED -	NSN 4220-01-487-3658
MEDIUM, BLUE -	NSN 4220-01-487-3209	X-LARGE, GREEN -	NSN 4220-01-487-3660
MEDIUM, BROWN -	NSN 4220-01-487-3238	X-LARGE, BLUE -	NSN 4220-01-487-3662
MEDIUM, YELLOW -	NSN 4220-01-487-3293	X-LARGE, BROWN -	NSN 4220-01-487-3665
		X-LARGE, YELLOW -	NSN 4220-01-487-3664
		X-LARGE, PURPLE -	NSN 4220-01-487-3668



NAVAIR RESCUE REPORT



An Update for Navy Aircraft Firefighters and Aircraft Handlers

2. Other associated equipment listed individually (prices are approximate)

Item	NSN	Cost
1. BLADDER	NSN 4220-01-487-2926	\$20
2. CO2 CYLINDER (24 GRAM)	4220-01-487-2878,	\$4
3. DISTRESS MARKER LIGHT (FIREFLY 2)	4220-01-487-2929	\$55
4. FLAT WHISTLE	4220-01-487-2931	\$2

The 2002 ABMA Symposium will be held at the Silverdale Hotel, in Silverdale, Washington, Aug 5-9. The room rate for active military is \$70.30 for either a 1-single bed, single occupancy; 1-double bed, double occupancy; or 2-bedded rooms with up to 4 people. Camper and RV rates are \$25.00 (no hook-ups avail). The Silverdale Hotel number is (360) 698-1000, FAX (360) 692-0932, or logon to their website at www.westcoasthotels.com/silverdale or email sdhotel@silverlik.net

For additional info log onto: <http://www.abma-usn.org>

NAVAIR RESCUE REPORT

*An Update for Navy Aircraft Firefighters
and Aircraft Handlers*



Agenda Item Update!!

Agenda Item 00-ABMA-045 P-25 Storage compartment.

TYCOMS expressed interest and fielded out to the fleet for input. Fleet desires were mixed. Those who disliked this initiative anticipated removing it from their units if installed. Since overall fleet desire is not mutual, this agenda item is closed with no further action. Ships still desiring local manufacturing and installation should contact NAWC Lakehurst for guidance and approval prior to installation MFFV's.

Agenda Item 00-ABMA-053 Tow bar causing damage to non-skid. ECP/RAMEC has been submitted to PMA-260 for engineering evaluation and recommended changes. This is possibly a locally manufactured repairable item and is under investigation to determine best possible solution. This item remains open. Last update 11 Mar 2002

Agenda Item 01-ABMA-ABH-004 Confusion IRT authorized slings/belly bands.

NAVAIR RESCUE REPORT



An Update for Navy Aircraft Firefighters and Aircraft Handlers

Questions from the fleet. *Is the Morning Pride Proximity Helmet authorized for the Hangar Deck Crash crew?*

Answer:

Yes! The *Morning Pride Proximity Helmet* **is** authorized for use in hangar deck and flight deck proximity fire fighting. It is **not** authorized for any other shipboard fire fighting application.

GFSI / SEC currently offers two proximity helmets;

Mfg.. (Model)	NFPA Certified?	Authorized for Flight Deck Use?	Authorized for Damage Control	Price
Morning Pride (MPR=HTBPRLFPLUSPROX02)	YES	YES	NO	\$255.00
Bullard (BUL=AX)	YES	YES	YES	\$430.00



NAVAIR RESCUE REPORT

An Update for Navy Aircraft Firefighters and Aircraft Handlers



Did you know? There is a new flight deck goggle and lens assembly replacement for the sun/wind/dust goggle currently used aboard ships?

ESS Flight Deck Goggle, Part number ESS 01CB-NV,
NSN 4210-01-492-5720, Price \$ 29.95 each

ESS Clear lens 50 pack, Part number EL4,
NSN 4210-01-492-5722 Price \$ 300.16 per pack

ESS Smoke lens 50 pack, Part number EL5,
NSN4210-01-492-5725 Price \$ 300.16 per pack

The goggles can also be purchased through the Navy's electronic POPS system or directly from the DLA prime vendor contractors listed below:

SAFETY EQUIPMENT COMPANY (SEC)

CUSTOMER SERVICE 1-800-226-4732

ZONES 1 AND 2, REGION EAST CONTRACT NUMBER SP0500-99-D-0020

ZONE 1, REGION WEST AND CENTRAL CONTRACT NUMBER SP0500-99-D-0059

LION VALLEN INDUSTRIES (LVI)

CUSTOMER SERVICE 1-888-848-5599

ZONE 3, REGION EAST CONTRACT NUMBER SP0500-99-D-0021

ZONE 2, REGION WEST AND CENTRAL CONTRACT NUMBER SP0500-99-D-0060



NAVAIR RESCUE REPORT

*An Update for Navy Aircraft Firefighters
and Aircraft Handlers*



Questions from the Fleet. *Are we authorized to change out our 2 1/2 inch hangar deck AFFF hoses to the 1 3/4 hoses since the rest of the ship has done so already?*

Answer:

No, not at this time. NAVSEA is still reviewing the change recommendation to authorize the exchange of all CV/CVN hangar deck 2 1/2 inch hoses down to 1 3/4 inch size. Justification is that the smaller hoses will allow for better hose control and less personnel required at the scene of fire. Authorization message to be forwarded once approved and released by NAVSEASYSKOM.

We are always looking for fleet news around the world to include in our newsletter. Send in your comments, questions or suggestions to LT Scott Dancer, Bldg. 2272, Suite 348, NAVAIRSYSCOM, 47123 Buse Rd. Unit IPT, Patuxent River, Md. 20670-1547, or call 301-757-6998, DSN 757-6998, Fax 301-757-6800 or email dancersr@navair.navy.mil Our next copy deadline will be the end of quarter.



This news letter is published by PMA-251F3/5 and is intended for U. S. Navy Aviation Fire Fighters and Aircraft Handlers. Information contained herein is of public knowledge and solely intended to inform fleet sailors of changes or impending changes to equipment, protective clothing, or procedures.